



# NEW!


## Bottom Side Extraction Tool for Damaged Sockets

In applications where pushing a damaged socket through the plate is not feasible, these tools enable socket removal by driving the socket out from the bottom side of the plate (termination end), minimizing damage to the plate and surrounding components.

Available in the following sizes, with optional replacement tips when the tips become worn or damaged.

### QA Technology is globally recognized for:

- Exceptional Product Performance
- Competitive Prices
- Fast Delivery
- Outstanding Service



Replacement Tip (2 pcs)

Product Series	Tool Part Number	TIP Part Number
100-16, 100-25 or 100-40	ETR100B	ETR100B-TIP
075-25 or 075-40	ETR075B	ETR075B-TIP
050-16, 050-25 or 050-40	ETR050B	ETR050B-TIP
039-16, 039-25 or 039-40	ETR039B	ETR039B-TIP



Instructions



Replacement

Please scan for instructions on how to use this tool and for tip replacement instructions.

For more information or pricing, please contact one of our **Customer Service Team** members at **603.926.0348** or visit [www.qatech.com](http://www.qatech.com)